

IECEX Quality Assessment Report: GB/SIR/QAR06.0020/07 details

QAR :

QAR Reference Number *: GB/SIR/QAR06.0020/07
(automatic numbering)

Related QARs: [GB/SIR/QAR06.0020/06](#)
[GB/SIR/QAR06.0020/05](#)
[GB/SIR/QAR06.0020/04](#)
[GB/SIR/QAR06.0020/03](#)
[GB/SIR/QAR06.0020/02](#)
[GB/SIR/QAR06.0020/01](#)
[GB/SIR/QAR06.0020/00](#)

Status*: Issued

QAR Free Reference Number*: 70134271

Audit Date*: 2017-09-05
(yyyy-mm-dd)

Date of Issue*: 2017-09-18
(yyyy-mm-dd)

Details of change*: Recertification Audit

Valid until*: 2020-10-21
(yyyy-mm-dd)

Site(s) audited*: European Safety Systems Limited
 Impress House
 Mansell Road
 Acton
 London W3 7QH

Issuing ExCB*: SIR - SIRA Certification Service

Manufacturer*: European Safety Systems Limited
 Impress House
 Mansell Road
 Acton
 London W3 7QH

Country of Manufacture*: United Kingdom

Product information*: sounders, beacons and loudspeakers

Protection concept*: Ex ia, d, e, t, mb, nA

Related IECEX Certificates:
(automatic linking)

Related Certificates:
(manual insertion) IECEX SIM 04.0001
 IECEX SIM 04.0002
 IECEX SIM 04.0003

Related IECEX Certificates
for previous versions:

ExCB


CoC and Status

Totals

14

[IECEX KEM 10.0002 issue: 0 \[Current\]](#)

[IECEX KEM 10.0002 issue: 1 \[Current\]](#)

[IECEX KEM 10.0002X issue: 2 \[Current\]](#)

[IECEX KEM 10.0002X issue: 3 \[Current\]](#)

[IECEx KEM 10.0003 issue: 0 \[Current\]](#)
[IECEx KEM 10.0003 issue: 1 \[Current\]](#)
[IECEx KEM 10.0003X issue: 2 \[Current\]](#)
[IECEx KEM 10.0024X issue: 0 \[Current\]](#)
[IECEx KEM 10.0024X issue: 1 \[Current\]](#)
[IECEx KEM 10.0024X issue: 2 \[Current\]](#)
[IECEx KEM 10.0025X issue: 0 \[Current\]](#)
[IECEx KEM 10.0025X issue: 1 \[Current\]](#)
[IECEx KEM 10.0025X issue: 2 \[Current\]](#)
[IECEx KEM 10.0025X issue: 3 \[Current\]](#)

 SIR

24

[IECEx SIR 04.0038X issue: 0 \[Current\]](#)
[IECEx SIR 04.0038X issue: 1 \[Current\]](#)
[IECEx SIR 04.0038X issue: 2 \[Current\]](#)
[IECEx SIR 04.0038X issue: 3 \[Current\]](#)
[IECEx SIR 04.0038X issue: 4 \[Current\]](#)
[IECEx SIR 04.0039X issue: 0 \[Current\]](#)
[IECEx SIR 04.0039X issue: 1 \[Current\]](#)
[IECEx SIR 04.0039X issue: 2 \[Current\]](#)
[IECEx SIR 04.0039X issue: 3 \[Current\]](#)
[IECEx SIR 04.0039X issue: 4 \[Current\]](#)
[IECEx SIR 06.0045X issue: 0 \[Current\]](#)
[IECEx SIR 06.0045X issue: 1 \[Current\]](#)
[IECEx SIR 06.0045X issue: 2 \[Current\]](#)
[IECEx SIR 08.0020X issue: 0 \[Current\]](#)
[IECEx SIR 09.0121X issue: 0 \[Current\]](#)
[IECEx SIR 09.0121X issue: 1 \[Current\]](#)
[IECEx SIR 09.0121X issue: 2 \[Current\]](#)
[IECEx SIR 09.0121X issue: 3 \[Current\]](#)
[IECEx SIR 09.0122X issue: 0 \[Current\]](#)
[IECEx SIR 09.0122X issue: 1 \[Current\]](#)
[IECEx SIR 10.0073 issue: 0 \[Current\]](#)
[IECEx SIR 10.0073 issue: 1 \[Current\]](#)
[IECEx SIR 13.0029X issue: 0 \[Current\]](#)
[IECEx SIR 15.0116X issue: 0 \[Current\]](#)

 UL

2

[IECEx UL 15.0003X issue: 0 \[Current\]](#)
[IECEx UL 15.0003X issue: 1 \[Current\]](#)

 ULD

9

[IECEx ULD 14.0004X issue: 0 \[Current\]](#)
[IECEx ULD 14.0004X issue: 1 \[Current\]](#)
[IECEx ULD 14.0004X issue: 2 \[Current\]](#)
[IECEx ULD 14.0012X issue: 0 \[Current\]](#)
[IECEx ULD 14.0012X issue: 1 \[Current\]](#)

[IECEX ULD 15.0018X issue: 0 \[Current\]](#)

[IECEX ULD 15.0018X issue: 1 \[Current\]](#)

[IECEX ULD 16.0017X issue: 0 \[Current\]](#)

[IECEX ULD 16.0017X issue: 1 \[Current\]](#)

Comment:

Attachment:
