



# IECEx Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.:	<b>GB/SIR/QAR06.0020/08</b>	Page 1 of 2
QAR Free Ref. No.:	<b>80001550</b>	Status: <b>Issued</b>
Details of change:	Surveillance Audit	Date of issue: <b>2019-04-29</b>
Site(s) audited:	<b>European Safety Systems Limited</b> Impress House Mansell Road Acton London W3 7QH <b>United Kingdom</b>	Valid until: <b>2021-04-21</b>  Audit date: <b>2019-04-23</b>
Issuing ExCB:	<b>SIR - SIRA Certification Service</b>	
Manufacturer:	<b>European Safety Systems Limited</b> Impress House Mansell Road Acton London W3 7QH	
Location of Manufacturer:	<b>United Kingdom</b>	
Product information:	sounders, beacons and loudspeakers	
Protection concept:	<b>Ex ia, d, e, t, mb, nA</b>	
Related QARs:		
GB/SIR/QAR06.0020/00	GB/SIR/QAR06.0020/01	GB/SIR/QAR06.0020/02
GB/SIR/QAR06.0020/03	GB/SIR/QAR06.0020/04	GB/SIR/QAR06.0020/05
GB/SIR/QAR06.0020/06	GB/SIR/QAR06.0020/07	

### Related Certificates (manual insertion)::

**IECEx SIM 04.0001**  
**IECEx SIM 04.0002**  
**IECEx SIM 04.0003**

### Related Certificates (automatic linking)::

IECEx SIR 04.0038X issue: 5	IECEx SIR 04.0039X issue: 5	IECEx ULD 14.0004X issue: 4
IECEx SIR 10.0073 issue: 2	IECEx SIR 09.0121X issue: 6	IECEx SIR 09.0122X issue: 2
IECEx UL 15.0003X issue: 2	IECEx SIR 09.0121X issue: 5	IECEx SIR 13.0029X issue: 1
IECEx SIR 06.0045X issue: 3		

### Related Certificates for previous versions:

IECEx KEM 10.0002 issue: 0	IECEx KEM 10.0002 issue: 1	IECEx KEM 10.0002X issue: 2
IECEx KEM 10.0002X issue: 3	IECEx KEM 10.0002X issue: 4	IECEx KEM 10.0003 issue: 0
IECEx KEM 10.0003 issue: 1	IECEx KEM 10.0003X issue: 2	IECEx KEM 10.0003X issue: 3
IECEx KEM 10.0024X issue: 0	IECEx KEM 10.0024X issue: 1	IECEx KEM 10.0024X issue: 2
IECEx KEM 10.0024X issue: 3	IECEx KEM 10.0025X issue: 0	IECEx KEM 10.0025X issue: 1
IECEx KEM 10.0025X issue: 2	IECEx KEM 10.0025X issue: 3	IECEx KEM 10.0025X issue: 4
IECEx SIR 04.0038X issue: 0	IECEx SIR 04.0038X issue: 1	IECEx SIR 04.0038X issue: 2
IECEx SIR 04.0038X issue: 3	IECEx SIR 04.0038X issue: 4	IECEx SIR 04.0039X issue: 0
IECEx SIR 04.0039X issue: 1	IECEx SIR 04.0039X issue: 2	IECEx SIR 04.0039X issue: 3
IECEx SIR 04.0039X issue: 4	IECEx SIR 06.0045X issue: 0	IECEx SIR 06.0045X issue: 1
IECEx SIR 06.0045X issue: 2	IECEx SIR 08.0020X issue: 0	IECEx SIR 09.0121X issue: 0
IECEx SIR 09.0121X issue: 1	IECEx SIR 09.0121X issue: 2	IECEx SIR 09.0121X issue: 3
IECEx SIR 09.0121X issue: 4	IECEx SIR 09.0122X issue: 0	IECEx SIR 09.0122X issue: 1



# IECEx Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR06.0020/08**

Page 2 of 2

Related Certificates for  
previous versions (continued):

IECEx SIR 10.0073 issue: 0  
IECEx SIR 15.0116X issue: 0  
IECEx ULD 14.0004X issue: 0  
IECEx ULD 14.0004X issue: 3  
IECEx ULD 15.0018X issue: 0  
IECEx ULD 16.0017X issue: 1  
IECEx ULD 19.0007X issue: 0

IECEx SIR 10.0073 issue: 1  
IECEx UL 15.0003X issue: 0  
IECEx ULD 14.0004X issue: 1  
IECEx ULD 14.0012X issue: 0  
IECEx ULD 15.0018X issue: 1  
IECEx ULD 19.0006X issue: 0  
IECEx ULD 19.0008X issue: 0

IECEx SIR 13.0029X issue: 0  
IECEx UL 15.0003X issue: 1  
IECEx ULD 14.0004X issue: 2  
IECEx ULD 14.0012X issue: 1  
IECEx ULD 16.0017X issue: 0  
IECEx ULD 19.0006X issue: 1

Comments: