



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.: **GB/SIR/QAR06.0020/09** Page 1 of 2

QAR Free Ref. No.: **80053872/3** Status: **Issued**

Details of change: Recertification Audit Date of issue: **2020-10-28**

Site(s) audited: **European Safety Systems Limited** Valid until: **2023-10-21**  
Impress House  
Mansell Road  
Acton  
London W3 7QH  
**United Kingdom** Audit date: **2020-10-28**

Issuing ExCB: **SIR - SIRA Certification Service**

Manufacturer: **European Safety Systems Limited**  
Impress House  
Mansell Road  
Acton  
London W3 7QH

Location of Manufacturer: **United Kingdom**

Product information: sounders, beacons and loudspeakers

Protection concept: **Ex ia, d, e, t, mb, nA**

Related QARs:

GB/SIR/QAR06.0020/00	GB/SIR/QAR06.0020/01	GB/SIR/QAR06.0020/02
GB/SIR/QAR06.0020/03	GB/SIR/QAR06.0020/04	GB/SIR/QAR06.0020/05
GB/SIR/QAR06.0020/06	GB/SIR/QAR06.0020/07	GB/SIR/QAR06.0020/08

Related Certificates (manual insertion)::

**IECEX SIM 04.0001**  
**IECEX SIM 04.0002**  
**IECEX SIM 04.0003**

Related Certificates (automatic linking)::

Related Certificates for  
previous versions:

IECEX KEM 10.0002 issue: 0	IECEX KEM 10.0002 issue: 1	IECEX KEM 10.0002X issue: 2
IECEX KEM 10.0002X issue: 3	IECEX KEM 10.0002X issue: 4	IECEX KEM 10.0003 issue: 0
IECEX KEM 10.0003 issue: 1	IECEX KEM 10.0003X issue: 2	IECEX KEM 10.0003X issue: 3
IECEX KEM 10.0024X issue: 0	IECEX KEM 10.0024X issue: 1	IECEX KEM 10.0024X issue: 2
IECEX KEM 10.0024X issue: 3	IECEX KEM 10.0025X issue: 0	IECEX KEM 10.0025X issue: 1
IECEX KEM 10.0025X issue: 2	IECEX KEM 10.0025X issue: 3	IECEX KEM 10.0025X issue: 4
IECEX SIR 04.0038X issue: 0	IECEX SIR 04.0038X issue: 1	IECEX SIR 04.0038X issue: 2
IECEX SIR 04.0038X issue: 3	IECEX SIR 04.0038X issue: 4	IECEX SIR 04.0038X issue: 5
IECEX SIR 04.0039X issue: 0	IECEX SIR 04.0039X issue: 1	IECEX SIR 04.0039X issue: 2
IECEX SIR 04.0039X issue: 3	IECEX SIR 04.0039X issue: 4	IECEX SIR 04.0039X issue: 5
IECEX SIR 06.0045X issue: 0	IECEX SIR 06.0045X issue: 1	IECEX SIR 06.0045X issue: 2
IECEX SIR 06.0045X issue: 3	IECEX SIR 08.0020X issue: 0	IECEX SIR 09.0121X issue: 0
IECEX SIR 09.0121X issue: 1	IECEX SIR 09.0121X issue: 2	IECEX SIR 09.0121X issue: 3
IECEX SIR 09.0121X issue: 4	IECEX SIR 09.0121X issue: 5	IECEX SIR 09.0121X issue: 6
IECEX SIR 09.0122X issue: 0	IECEX SIR 09.0122X issue: 1	IECEX SIR 09.0122X issue: 2
IECEX SIR 10.0073 issue: 0	IECEX SIR 10.0073 issue: 1	IECEX SIR 10.0073 issue: 2
IECEX SIR 13.0029X issue: 0	IECEX SIR 13.0029X issue: 1	IECEX SIR 15.0116X issue: 0



# IECEx Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR06.0020/09**

Page 2 of 2

Related Certificates for  
previous versions (continued):

IECEx UL 15.0003X issue: 0  
IECEx ULD 14.0004X issue: 0  
IECEx ULD 14.0004X issue: 3  
IECEx ULD 14.0012X issue: 1  
IECEx ULD 16.0017X issue: 0  
IECEx ULD 19.0006X issue: 1

IECEx UL 15.0003X issue: 1  
IECEx ULD 14.0004X issue: 1  
IECEx ULD 14.0004X issue: 4  
IECEx ULD 15.0018X issue: 0  
IECEx ULD 16.0017X issue: 1  
IECEx ULD 19.0007X issue: 0

IECEx UL 15.0003X issue: 2  
IECEx ULD 14.0004X issue: 2  
IECEx ULD 14.0012X issue: 0  
IECEx ULD 15.0018X issue: 1  
IECEx ULD 19.0006X issue: 0  
IECEx ULD 19.0008X issue: 0

Comments: