

## IECEx Quality Assessment Report Summary

Audit date: 2023-10-26

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **GB/SIR/QAR06.0020/12** Page 1 of 2

QAR Free Ref. No.: 80182321-80182322 Status:Issued

Details of change: Recertification Audit Date of issue:2023-10-05

Location(s) audited: European Safety Systems Limited Valid until:2026-10-21

Impress House Mansell Road

Acton

London W3 7QH United Kingdom

Issuing ExCB: SIR - CSA Group Testing UK Ltd

Manufacturer: European Safety Systems Limited

Impress House Mansell Road Acton

London W3 7QH

Location of United Kingdom

Manufacturer:

Product information: sounders, beacons and loudspeakers

Type of protection: Ex ia, d, e, t, mb, nA

Related QARs:

GB/SIR/QAR06.0020/00 GB/SIR/QAR06.0020/01 GB/SIR/QAR06.0020/02 GB/SIR/QAR06.0020/03 GB/SIR/QAR06.0020/04 GB/SIR/QAR06.0020/05 GB/SIR/QAR06.0020/06 GB/SIR/QAR06.0020/07 GB/SIR/QAR06.0020/08 GB/SIR/QAR06.0020/10 GB/SIR/QAR06.0020/11

Related Certificates (manual insertion)::

IECEX SIM 04.0001 IECEX SIM 04.0002 IECEX SIM 04.0003

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEx KEM 10.0002 issue: 0 IECEx KEM 10.0002 issue: 1 IECEx KEM 10.0002X issue: 2 IECEx KEM 10.0002X issue: 3 IECEx KEM 10.0002X issue: 4 IECEx KEM 10.0002X issue: 5 IECEx KEM 10.0003 issue: 0 IECEx KEM 10.0003 issue: 1 IECEx KEM 10.0003X issue: 2 IECEx KEM 10.0003X issue: 3 IECEx KEM 10.0003X issue: 4 IECEx KEM 10.0024X issue: 0 IECEx KEM 10.0024X issue: 1 IECEx KEM 10.0024X issue: 2 IECEx KEM 10.0024X issue: 3 IECEx KEM 10.0025X issue: 0 IECEx KEM 10.0025X issue: 1 IECEx KEM 10.0025X issue: 2 IECEx KEM 10.0025X issue: 3 IECEx KEM 10.0025X issue: 4 IECEx SIR 04.0038X issue: 0 IECEx SIR 04.0038X issue: 1 IECEx SIR 04.0038X issue: 2 IECEx SIR 04.0038X issue: 3 IECEx SIR 04.0039X issue: 0 IECEx SIR 04.0038X issue: 4 IECEx SIR 04.0038X issue: 5 IECEx SIR 04.0039X issue: 2 IECEx SIR 04.0039X issue: 1 IECEx SIR 04.0039X issue: 3 IECEx SIR 06.0045X issue: 0 IECEx SIR 04.0039X issue: 4 IECEx SIR 04.0039X issue: 5 IECEx SIR 06.0045X issue: 3 IECEx SIR 06.0045X issue: 1 IECEx SIR 06.0045X issue: 2 IECEx SIR 09.0121X issue: 0 IECEx SIR 06.0045X issue: 4 IECEx SIR 08.0020X issue: 0 IECEx SIR 09.0121X issue: 3 IECEx SIR 09.0121X issue: 1 IECEx SIR 09.0121X issue: 2 IECEx SIR 09.0121X issue: 4 IECEx SIR 09.0121X issue: 6 IECEx SIR 09.0121X issue: 5 IECEx SIR 09.0122X issue: 0 IECEx SIR 09.0122X issue: 2 IECEx SIR 09.0122X issue: 1 IECEx SIR 10.0073 issue: 0 IECEx SIR 10.0073 issue: 1 IECEx SIR 10.0073 issue: 2 IECEx SIR 13.0029X issue: 0 -- Continued on the next page IECEx SIR 13.0029X issue: 1 IECEx SIR 15.0116X issue: 0



## IECEx Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR06.0020/12** Page 2 of 2

Related Certificates for previous versions (continued):

IEOE: III 45 0000V : 0	IEOE: III 45 0000V : 4	IEOE. III 45 0000V : 0
IECEx UL 15.0003X issue: 0	IECEx UL 15.0003X issue: 1	IECEx UL 15.0003X issue: 2
IECEx UL 15.0003X issue: 3	IECEx ULD 14.0004X issue: 0	IECEx ULD 14.0004X issue: 1
IECEx ULD 14.0004X issue: 2	IECEx ULD 14.0004X issue: 3	IECEx ULD 14.0004X issue: 4
IECEx ULD 14.0004X issue: 5	IECEx ULD 14.0004X issue: 6	IECEx ULD 14.0004X issue: 7
IECEx ULD 14.0012X issue: 0	IECEx ULD 14.0012X issue: 1	IECEx ULD 14.0012X issue: 2
IECEx ULD 15.0018X issue: 0	IECEx ULD 15.0018X issue: 1	IECEx ULD 15.0018X issue: 2
IECEx ULD 15.0018X issue: 3	IECEx ULD 16.0017X issue: 0	IECEx ULD 16.0017X issue: 1
IECEx ULD 16.0017X issue: 2	IECEx ULD 16.0017X issue: 3	IECEx ULD 16.0017X issue: 4
IECEx ULD 19.0006X issue: 0	IECEx ULD 19.0006X issue: 1	IECEx ULD 19.0007X issue: 0
IECEx ULD 19.0007X issue: 1	IECEx ULD 19.0007X issue: 2	IECEx ULD 19.0008X issue: 0
IECEx ULD 19.0008X issue: 1	IECEx ULD 19.0008X issue: 2	

Comments: