

消 防 處
牌 照 及 審 批 總 區
香 港 九 龍 尖 沙 咀 東 康 莊 道 1 號 5 樓
消 防 總 部 大 廈



**FIRE SERVICES DEPARTMENT
LICENSING AND CERTIFICATION
COMMAND**

FIRE SERVICES HEADQUARTERS BUILDING,
No.1 Hong Chong Road, 5/F,
Tsim Sha Tsui East Kowloon,
Hong Kong.

本處編號 OUR REF.: (18) in FP 206/1165
來函編號 YOUR REF.:
電子郵件 E-mail <lcpolice2@hkfsd.gov.hk>
圖文傳真 FAX: 852-2723 2197
電 話 TEL NO.: 852-2733 7557

16 January 2007

European Safety Systems Ltd.
Impress House, Mansell Road
London
UK W3 7QH

Dear Sirs,

Acceptance of IS Mini Alarm Product in Hong Kong

I refer to my interim reply of 22 November 2006 on the captioned subject.

Please be informed that the following equipment, which has been certified by Sira Certification Service, is acceptable for use in hazardous locations in Hong Kong:

- | | |
|-----------------------------|--|
| Manufacturer | : European Safety Systems Limited |
| Type | : Combined Sounder / Beacon |
| Model | : IS-mC1 |
| Assessment Standards | : Potentially Explosive Atmospheres Directive 94/9/EC;
EN 50014 : 1997 + A1 and A2;
EN 50020: 2002; and
EN 50284: 1999 |
| Supporting Documents | : i) EC-Type Examination Certificate No. Sira
05ATEX2084X dated 18 August 2006 (Latest
issue) issued by Sira Certification Service;
ii) Assessment Report No. R52A13291A dated July
2005 issued by Sira Test & Certification Ltd.;
iii) Re-issue Reports No. R52A14305 and
R52A15304A dated November 2005 and July 2006
respectively issued by Sira Test & Certification
Ltd.; and
iv) Variation Report No. R52A14095A dated October
2005 issued by Sira Test & Certification Ltd. |

.../P.2

Please note that the above acceptance is subject to :

- i) all the conditions stated in the above-mentioned Reports and certificate, in particular the followings, being complied with ;
 - a) The conditions as stipulated in the special conditions for safe use specified for IS-mC1 combined sounder/beacon in Paragraph 15.3 of the Schedule to the above EC Type-Examination Certificate;
 - b) Essential health and safety requirements (EHSRs) of Annex II of the Directive 94/9/EC (EHSRs that are not addressed by the standards but listed in the Certificate and are identified and individually assessed in the above mentioned reports); and
 - c) The production control requirements defined in Article B of Directive 94/9/EC.
- ii) The installation conforming to FSD Circular Letter No. 1/2002 Rules for Fire Detection and Alarm Systems for Buildings; and
- iii) Any other additional requirements which may be imposed by this Department being complied with.

Yours faithfully,


(YAU Chi-on)
for Director of Fire Services

c.c. DEMS
(Ref. Ref. (28) in CI/21/04 Pt. 33)

OUR REF.: (18) in FP 206/1165

YCO/aywc

消 防 處
牌 照 及 審 批 總 區
香 港 九 龍 尖 沙 咀 東 康 莊 道 1 號 5 樓
消 防 總 部 大 廈



FIRE SERVICES DEPARTMENT
LICENSING AND CERTIFICATION COMMAND
FIRE SERVICES HEADQUARTERS BUILDING,
5/F, No.1 Hong Chong Road,
Tsim Sha Tsui East, Kowloon,
Hong Kong.

本處檔號 OUR REF.:(19) in FP 206/1165
來函檔號 YOUR REF.:
電子郵件 E-mail : <lcpolice2@hkfsd.gov.hk>
圖文傳真 FAX : 852-2367 3631
電 話 TEL NO. : 852-2733 7557

16 January 2007

European Safety Systems Ltd.
Impress House, Mansell Road
London
UK W3 7QH

Dear Sirs,


Application for Acceptance of IS mini Alarm Product Range in Hong Kong

I refer to my interim reply of 22 November 2006 on the captioned subject.

Please be informed that according to FSD Circular Letter No. 4/98, product approval of Audio/Visual Advisory System including sounder and beacon (with the exception of combined sounder/beacon) is not required. Nevertheless, components in a Fire Detection and Alarm Systems shall be installed in accordance with FSD Circular Letter No. 1/2002 Rules for Fire Detection and Alarm Systems for Buildings and shall be compatible with other devices in the system.

Please feel free to call our Mr. AU YEUNG Wai-cheung at Tel no. 852-2733 7557 during office hours for any other questions.

Yours faithfully,


(YAU Chi-on)
for Director of Fire Services

YCO/aywc