

Certificate of Compliance

Certificate Number:

UL-US-2580679-1

Report Reference:

E230764-20220525

Issue Date:

2025-10-07

Issued to:

**European Safety Systems Ltd
Impress House
Mansell Rd. London W3 7QH
United Kingdom**

This certificate confirms that representative samples of:

**UXVD - Audible-signal Appliances, Fire Alarm, for Use in Zone
Classified Hazardous Locations**

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

**UL 464, Edition 11, Issue Date 2023-04-28, UL 60079-0, Edition: 7,
Issue Date: 2019-3-26, Revision Date: 2020-4-15, UL 60079-1,
Edition: 7, Issue Date: 2015-9-18, Revision Date: 2020-1-23**

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



A handwritten signature in black ink that reads 'David Piecuch'.

David Piecuch
UL Mark Certification Program Owner

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

CERTIFICATE OF COMPLIANCE

Certificate number UL-US-2580679-1
Report reference E230764-20220525
Date 2025-10-07

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Sounders

Model(s): STExS1FDC024-A, STExS1FDC024-S, STExS1RDC024-A, STExS1RDC024-S, STExS2FDC024-A, STExS2FDC024-S, STExS2HDC024-A, STExS2HDC024-S



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

Certificate of Compliance

Certificate Number:

UL-CA-2559146-1

Report Reference:

E230764-20220525

Issue Date:

2025-10-07

Issued to:

**European Safety Systems Ltd
Impress House
Mansell Rd. London W3 7QH
United Kingdom**

This certificate confirms that representative samples of:

**UXVD7 - Audible-signal Appliances, Fire Alarm, for Use in Zone
Classified Hazardous Locations Certified for Canada**

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

ULC 525:2023, 5th Ed., Issue Date: 2023-04-28, CSA C22.2 No. 60079-0, Edition 3, Issued 2015-10-01, CSA C22.2 NO. 60079-1, 3rd Ed., Issue Date: 2016-05-01

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch
UL Mark Certification Program Owner



CERTIFICATE OF COMPLIANCE

Certificate number UL-CA-2559146-1
Report reference E230764-20220525
Date 2025-10-07

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Combined Sounder/Beacons, General Signalling

Model(s): STExC1X05AC230, STExC1X05DC024

Sounders

Model(s): STExS1FDC024-A, STExS1FDC024-S, STExS1RDC024-A, STExS1RDC024-S, STExS2FDC024-A, STExS2FDC024-S, STExS2HDC024-A, STExS2HDC024-S



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

Certificate of Compliance

Certificate Number:

UL-US-2315264-2

Report Reference:

E230764-20220525

Issue Date:

2025-10-07

Issued to:

**European Safety Systems Ltd
Impress House
Mansell Rd. London W3 7QH
United Kingdom**

This certificate confirms that representative samples of:

**UXVF - Audible-signal Appliances for Use in Zone Classified
Hazardous Locations**

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

UL 464A, Edition 1, Issue Date 2016-02-03, Revision Date 2025-07-09, UL 60079-0, Edition: 7, Issue Date: 2019-3-26, Revision Date: 2020-4-15, UL 60079-1, Edition: 7, Issue Date: 2015-9-18, Revision Date: 2020-1-23

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch
UL Mark Certification Program Owner



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

CERTIFICATE OF COMPLIANCE

Certificate number UL-US-2315264-2
Report reference E230764-20220525
Date 2025-10-07

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Combined Sounder/Beacons, General Signalling

Model(s): STExC1X05AC230, STExC1X05DC024

Sounders

Model(s): STExS1FDC024-A, STExS1FDC024-S, STExS1RDC024-A, STExS1RDC024-S, STExS2FDC024-A, STExS2FDC024-S, STExS2HDC024-A, STExS2HDC024-S

Sounders, General Signalling

Model(s): STExS1AC230, STExS1FAC230-A, STExS1RAC230-A, STExS2AC230, STExS2FAC230-A, STExS2HAC230-A



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

Certificate of Compliance

Certificate Number:

UL-CA-2313349-2

Report Reference:

E230764-20220525

Issue Date:

2025-10-07

Issued to:

**European Safety Systems Ltd
Impress House
Mansell Rd. London W3 7QH
United Kingdom**

This certificate confirms that representative samples of:

**UXVF7 - Audible-signal Appliances for Use in Zone Classified
Hazardous Locations Certified for Canada**

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

**CSA C22.2 NO. 60079-0, Edition 4, Issue Date: 2019-02-01, CSA
C22.2 NO. 60079-1, 3rd Ed., Issue Date: 2016-05-01, CSA C22.2
No. 205, Edition 3, Issued 2017-05-01**

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch
UL Mark Certification Program Owner



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

CERTIFICATE OF COMPLIANCE

Certificate number UL-CA-2313349-2
Report reference E230764-20220525
Date 2025-10-07

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Combined Sounder/Beacons, General Signalling

Model(s): STExC1X05AC230, STExC1X05DC024

Sounders

Model(s): STExS1FDC024-A, STExS1FDC024-S, STExS1RDC024-A, STExS1RDC024-S, STExS2FDC024-A, STExS2FDC024-S, STExS2HDC024-A, STExS2HDC024-S

Sounders, General Signalling

Model(s): STExS1AC230, STExS1FAC230-A, STExS1RAC230-A, STExS2AC230, STExS2FAC230-A, STExS2HAC230-A



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.